



SERVICE REPORT

PJS POWER SERVICE CENTER

20-3-88D/2/2, Sivajyothi Nagar, Tirumala Bypass Rd, near Leela Mahal
Road, opp. Narasari Garden, Tirupati, Andhra Pradesh 517501.
Phone: 7036019322. Email: pjspowerservicecenter@gmail.com

RECORD COPY

Customer Details:-

Task Id:-

Task Title:- Collection of Data from google

Created At:- 2025-05-31 10:47:53

Nature of Call: Heidolph Hei-CHILL 600 Chiller - Serial No./:CN 19000471 Reported/
suspected refrigerant gas loss. System performance issue.

Reported by: Mr Nandam Jayasurya

Service Engineer: Mr Jamalsaheb Palagiri

Engineer's Remark:-

SUMMARY OF FINDINGS

During a systematic leak check of the refrigeration system, a significant gas leak was confirmed at the compressor gas charging nipple (service port). The leak was identified using state method used: bubble solution.

A subsequent inspection of the refrigerant receiver tank and all condenser units was performed. No leaks were detected at these components.

Parts Used for Service:-

Parts Recommended:-

Customer Remark:-

Service Engineer:- Jabeer Palagiri
Engineer Sign:-

Date:- 2025-12-03 11:58:50
Customer Sign:-